

## CERTIFICATE OF PRACTICAL COMPLETION

Issued by: Volute Architect Limited

Address: 22 Merton Green, Caerwent, Monmouthshire, NP26 5AT Document ID: 20-1009-PRA

Employer: Netherwent Ministry Area Job Reference: 20-1009

Address: Ministry Area Office, Magor Church Centre, Chapel Terrace, Certificate No: PRA 01

Magor, NP26 5ET

Contractor: Taliesin Conservation,

Address: Britannia Centre for Enterprise, Pengam, Blackwood, NP12 3SP

Works: Internal and external repairs and upgrades to the porch and Issue Date: 24/07/2023

internal redecoration to the east wall of the sanctuary

Situated at: The church of St Stephen & St Tathan, Pound Lane, Caerwent,

NP26 5AY

I hereby certify that in my opinion Practical Completion of the Works has been achieved and the Contractor has complied with the specification and design intent on

the drawings on  $24^{th}$  July 2023

Signed

For and on behalf of Volute Architects